The contribution payable will vary proportionately in the event the estimate is revised; the atchkatdars are liable to pay at any suitably altered rates, if such a necessity to revise the estimate should arise.

Objections and suggestions, if any, to take up the work may be preferred in writing within thirty days from the date of this notification at the office of the Assistant Engineer, No. 1 Sub-Division, P.W.D., Kolar, and produce evidence, if any, in support of such objections and suggestions. Objections preferred after the expiry of the time limit, will not be entertained.

Further, the atchkatdars are required to be present at 3 P.M. on 20th October 1954 at the Pravasimandir, Mulbagal, for enquiry under Irrigation Act and to execute matchalika, binding to pay their share of contribution and assessment as specified.

.5171 N. GUNDU RAO, *Asst. Engr. and Irgn. Officer.*

OFFICE OF THE ASSISTANT ENGINEER AND IRRIGATION OFFICER, NO. 2 SUB-DIVISION, BANGARPET, P.W.D., KOLAR DISTRICT.

Notification dated 10th September 1954.

Under Section 29 (1) of the Mysore Irrigation Act as amended and VII of 1938 and VII of 1952, the following Irrigation works with detailed particulars involving levy of water rate and contribution are here by notified for the information of the public concerned. Any representation on the subject from any of the concerned ryots may be preferred before the undersigned in his office during office hours within thirty days from the last date of publication in the *Mysore Gazette*, after which no representation will be entertained.

Sl. No.	Name of Village	Name of Tank	Nature of Work	Tank Sl. No.	Tank Reg. No.	Amount of Estimate.	Amount of Contribution.	Atchkat Existing Kharab Acres	Kharab Guntas	Kharab Water Rate	Remarks
			KAMASAMUDRAM HOBLI, BANGARPET TALUK.								
1	Kamasamudram	Channegowdana-kere.	Closing lease and Strehgthening Perculation.	452	...	618	154	6 ...	... ...	...	Work Completed.
2	Bathlur ...	Kodagikere ...	Repairs to Sluice and waste weir	664	...	1,437	359	7 6	... ...	...	Do
3	Gattahalli ...	Naranappanakere	Repairs to Sluice and waste weir	196	704	1,860	465	4 ...	... ...	...	Do
4	Balamande ...	Koralakere ...	Repairs to Bund and Sluice ...	451	...	2,010	502	9 ...	... ...	...	Do
5	Do ...	Nainkere ...	Repairs to Bund and Sluice ...	450	...	900	448	6 ...	.. ...	...	Do
6	Do ...	Do ...	Earthwork and repairs to weir ...	...	...	890					
7	Bandarahalli ...	Naleygowdana-kere.	Repairs to Sluice and weir ...	649	...	2,523	631	6 ...	... ...	...	Do
8	Thoppanahalli ...	Kotekere ...	Repairs to Sluice and weir ...	650	460	2,663	1,498	11 ...	.. ...	...	Do
9	Do ...	Do ...	Construction of C.I. Pipe Sluice and weir.	...	...	3,330					
10	Gullahalli ...	Dasankere ...	Construction of Masonry body wall.	200	...	1,400	350	11 ...	... ...	...	Do
11	Gandahalli ...	Krishnankere ...	Repairs to Bund and Sluice body wall.	665	...	767	191	4 ...	... ...	...	Work Stop.
12	Bangar Natha ...	Voddu ...	Repairs to Voddu ...	...	...	1,000	250	18 ...	... ...	...	Work Completed.
13	Kenduli Mande ...	Voddu ...	Repairs to Voddu ...	...	...	1,300	325	18 ...	... ...	...	Do
14	Palamadagu ...	Voddu ...	Repairs to Voddu ...	...	...	2,500	625	18 ...	... ...	...	Do
15	Ukkarahalli ...	Neralakere ...	Desilting and Construction of C.I. Pipe Sluice.	105	...	1,674	419	10 ...	... ...	...	Do
16	Patha Ramagalla	Kodagekere ...	Providing revetment and waste weir.	191	...	1,755	439	6 ...	... ...	...	Do
17	Nadampalli ...	Doddakere ...	Improvements to Bund and Turfing.	635	379	840	210	19 ...	... ...	...	Do
18	Muthanur ...	Marappagowdana-kere.	Desilting work	...	...	1,900	475	13 ...	... ...	...	Do
19	Bodaguruki ...	Earappanakere ...	Desilting and closing leak ...	631	...	1,430	360	5 ...	... ...	...	Do
20	Thoppanahalli ...	Chintalkere ...	Desilting and closing leak ...	652	...	2,209	619	11 ...	... ...	...	Do
21	Do ...	Do ...	Closing leak	...	...	270					
22	Chinkamanahalli	Deverakere ...	Construction W. Weir and Sluice	659	...	1,650	412	6 ...	... ...	...	Final to be done.
23	Janagatta ...	Patharakere ...	Desilting Work	626	369	440	292	30 ...	... ...	...	Work Completed.
24	Do	Do ...	Do	...	...	150					
25	Do ...	Do	Do	...	...	600					
26	Thavarekere ...	Chayappanakere	Do	613	...	875	433	5 ...	... ...	...	Do
27	Do ...	Do ...	Constructing Masonry Weir ...	...	...	856					
28	Kadarenahalli ...	Kempiahnakere ..	Desilting Work	441	...	1,630	407	7 ...	... ...	...	Do
29	Gallahalli ...	Mudivinakere ...	Desilting Work and Construction of Weir and Sluice.	199	...	1,450	362	11 ...	... ...	...	Final to be done.
30	Patha Ramagalla	Janganakere ...	Construction of C.I. Pipe Sluice and Core Wall.	194	...	3,415	854	8 ...	... ...	...	Work Completed.
31	Madabays to Kamasamudram	Tank Channel ...	No. 1 F. and No. 2, Construction of C.I. Pipe Sluice and Core Wall Madabays.	...	...	6,820	1,705	600 ...	... ...	...	1 Work Completed. 2 Final to be given.
32	Providing Addi-tional Cross Bridge.	Kamasamudram Tank and Channel.	Construction of Cross Bridge ...	...	...	3,800	950	... ...	... ...	...	Work Completed.
33	Jakkapalli Gidda Kadarenahalli.	Kamasamudram Tank.	Constructing Wasteweir ...	625	...	1,031	257	6 ...	... ...	...	Work Completed.
34	Do ...	Construction of C.I. pipe sluice.	Do do ...	...	...						
35	Doddamaranahalli	Kondaibnakere ...	Closing the leak	440	...	400	100	4 ...	... ...	...	Do
36	Battarahalli Basavegowdana-kere.	Basavegowdana-kere.	Constructing C.I. Pipe Sluice ...	672	...	763	191	5 ...	... ...	...	Do
			BUDIKOTE HOBLI, BANGARPET TAULK.								
37	Gagiga ...	Puldikere ...	(a) Improvements to Bund ...	462	...	4,823	...	8 ...	... ...	...	Completed.
			(b) Resectioning the Bund ...	..	...						
			(c) Desilting the Bund ...	...	...						
38	Junjanahalli ...	Venkata Rao kere	(a) Desilting of Tank ...	421	...	8,800	...	17 ...	... ...	...	Do
			(b) Resorting the Tank ...	...	...						
			(c) Improvement to Bund and W. Weir and Sluice.	..	...						
			(d) Gravelling the Slopes ...	...	...						
39	Banahalli ...	Chintalkunte ...	Improvement to Bund and Wasteweir.	427	...	...	...	... ...	... ...	...	...
40	Do ...	Urumandinkere ...	Desilting the Bund Sluice Waste-weir.	...	...	3,058	...	5 ...	... ...	...	Completed.
			Closing Perculation Repairing the Pipe Sluice and Wasteweir.	430	...	1,515	...	20 ...	... ...	...	...
	Hunkala Doddi Tank.	Tank ...	Desilting the Tank Improvements to Bund and Wasteweir and Gravelling the Slopes.	431	...	3,117	...	8 ...	... ...	...	Completed.
	Yele Sandra ...	Neerinakere ...	Constructing Silt Dam ...	435	...	960	...	21 ...	... ...	...	Do
	Do ...	Karalakere ...	Improvements to Bund to Resto-ration, etc.	437	...	3,722	...	6 ...	... ...	...	Under Progress.

Sl. No.	Name of Village	Name of Tank	Nature of Work	Tank Sl. No.	Tank Reg. No.	Amount of Estimate.	Amount of Contribution.	Atchkat Kharab Existing Acres	Atchkat Kharab Existing Gunta	Water Rate	Remarks
44	Marandahalli ...	Sampangikere ...	Restoration of Tank ...	207	...	1,793	...	5 ...	... ...	...	Under Progress
45	Santiganahalli ...	Tank ...	Do	208	...	3,300	...	5 ...	... ...	...	...
46	Yachamanahalli...	Hongekere ...	Do	386	...	2,360	...	7 ...	... ...	...	Under Completion
47	Ukkunda ...	Gobrakere ...	Improvements to Bund and Sluice, etc.	381	...	2,460	2,460	29 ...	... ...	...	Do
48	Muganahalli ...	Voddu ...	Restoration of Voddu. Making good to damages due floods.	...	...	6,500	...	30 ...	... ...	...	Do
49	Kodaguruki ...	Tank ...	Approach Clearing to Wasteweir	431	...	2,600	...	42 ...	... ...	...	Do
50	Do ...	...	Do do ...	...	...						
			TYAKAL HOBLI, MALUR TALUK.								
51	Agara ...	Hongekere ...	Constructing C.I. Pipe Sluice of 6" and in Place of Damaged leaky Sluice.	352	160	784	196	36 30	... ...	...	Do
52	Thotagowdana-halli.	Amanikere ...	Construction R.W.W. across W. Weir urgent repairs to Sluice and W.W. and Turfing to Slopes.	353	171	1,705 / 1,550	814	87 16	... ...	...	Do
53	Halepalya ...	Giriyappanakere	Closing leaky and urgent repairs to Bund.	495	235	1,600	400	7 25	... ...	...	Under Progress.
54	Panamakanahalli	Doddakere ...	Restoring the Damaged Waste-weir, urgent repairs to Waste-weir and closing leaks in the Bund.	133	186	2,457	614	27 19	... ...	...	...
55	Nidaramangala ...	Chokkanathana-kere.	(a) Reconstructing the Damaged Wasteweir.	344	174	3,402	...	55 8	... ...	...	Work Completed.
			(b) Improving the Feeder Channel.	...	...	2,250	...	... 12	... ...	...	Do
			(c) Resectioning the Bund ...	...	...	3,416	...	... ...	... ...	...	Under Progress.
			(d) Raising the Wasteweir ..	...	...	1,300	...	... ...	... ...	...	Do
			(e) Turfing the Bund Slopes ...	...	...	1,500	2,967	... ...	... ...	...	Do
						11,868					
56	Anemittanahalli...	Pamalakunte ...	Repairs to Sluice ...	358	..	339	85	11 12	... ...	...	Completed.
57	Chicknaikanahalli	Rama Rajukere ...	Repairs to Sluice and Closing leaky in the Bund.	387	157	439	109	3 21	... ...	...	Do
58	Doddamale ...	Mainakere ...	Constructing C.I. Pipe Sluice of 6" Dia in place of Damaged leaky one.	316	206	815	204	2 32	... ...	...	Do
59	Do ...	Hosakere ...	Making good the Damages and repairing the Feeder Channel.	317	207	2,482	...	20 36	... ...	...	Do
60	Konda Settyhalli	Mavukere ...	Urgent repairs to Feeder Channel Do to Sluice Wasteweir and Turfing the Slopes.	335	133	1,220	...	11 20	... ...	...	Work Completed.
61	Somasandra ...	Kodagikere ...	Repairs to leaky Sluice and Bund Closing leaks and Scours.	363	229	1,027	412	10 3	... ...	...	Do
62	Yalaraguli ...	Biderkere ...	Constructing a Pipe Sluice ...	323	218	430	108	10 21	... ...	...	Do
63	Ullarahalli ...	Hongekere ...	Repairs to Sluice and Bund ...	355	223	960	240	22 22	... ...	...	Do
64	Banahalli ...	Doddakere ...	Restoring the Bund and Strengthening Bund, etc.	398	189	932 / 2,470	...	20 37	... ...	...	Do
65	Chickamalle ...	Kodagikere ...	Restoration:—	318	205	2,900	950	13 36	... ...	...	Do
			Urgent repairs to Sluice and Wasteweir, Turfing the Slopes.			3,3 0 / 1,350	1,718	... ...	... ...	...	Under Progress.
66	Byrathanahalli ...	Bandekere ...	Restoring the Damaged Weir, Closing leaky and Improvements	331	200	2,616 / 1,650	1,067	17 26	... ...	...	Do
67	Do ...	Mavukere ...	Closing leaks and repairs to Bund, Raising the Wasteweir.	332	201	2,778 / 950	932	16 3	... ...	...	Completed.
68	Do ...	Nakalikere ...	Constructing Masonry Sluice, etc.	329	202	1,400	350	5 25	... ...	...	Under Progress.
69	Hunisikote ...	Hongekere ...	Strengthing the Bund ...	357	238	4,500	1,125	33 17	... ...	...	Do
70	Kootiganahalli ...	Oorumundinakere	Desilting	351	147	4,000	1,000	29 24	... ...	...	Completed.
71	Obatti ...	Hongekere ...	Construction of Wasteweir and Sluice and Desilting.	492	226	3,100 / 3,000	1,525	3 13	... ...	...	Under Progress.
72	Ooriguruki ...	Gondalakere ...	Making Good the Flood Damage Caused to Wasteweir.	3,493	224	3,300	...	15 4	... ...	...	Do
73	Tyakal ...	Sonnenkere ...	Urgent repairs to Sluice ...	364	161	104	...	10 38	... ...	...	Work Completed.
74	Do ...	Easwarakere ...	Restoration	366	162	3,100	...	47 1	... ...	...	Do
75	Hullerahalli ...	Hongekere ...	Restoring	365	223	1,500	...	22 22	... ...	...	Work Under Progress.
76	Seethahalli ...	Doddakere ...	Construction of Silt Dam Extension of Wasteweir.	370	362	3,200 / 1,700	1,225	45 1	... ...	...	Do.
								137 36	... ...	...	Do
						4,900					
77	Huladanahalli ...	Doddakere ...	Urgent Repairs ...	320	369	598	...	... ...	... ...	...	Work Completed.
78	Badamakan halli	Gare Voddu ...	Repairs to Voddu and Channel ...	...	.	3 950	...	20 ...	... ...	...	Do
79	Pudasettihalli ..	Kodagikere ...	Closing leaks and urgent repairs to Sluice and Wasteweir.	325	184	4,250	...	8 38	... ...	...	Under Progress.
80	Tyakal ...	Bendekere ...	Closing leaks in the Bund ...	369	142	1,200	...	16 24	... ...	...	Do
81	Bettahalli ...	Bopadikunte ...	Earthwork to Bund C I. Pipe Sluice and Wasteweir.	407	...	1,900	...	3 33	... ...	...	Do
82	Kenchaganahalli	Tank ...	Repairs to Damaged Wasteweir	351	147	3,400	...	29 24	... ...	...	Do
83	Agara ...	Nagi Reddykere	(a) Closing the leaks in the Bund	539	184	901	...	22 8	... ...	...	Do
			(b) Wasteweir Restoration ...	...	...	1,800	..	... ...	... ...	...	Do
			(c) Strengthening the Bund ...	...	...	350					
			(d) Turfing the Slopes ...	...	...	1,100 / 1,200	1,587	... ...	... ...	...	Do
84	Halepalya ...	Venkatekere ...	Raising the Wasteweir Restoring the Bund.	494	234	1,400 / 850	662	23 38	... ...	...	Do
								... ...	... ...	...	Work Completed.

4833 N. NAGAPPA, *Asst. Engr. and Irrigation Officer.*

OFFICE OF THE ASSISTANT ENGINEER, SPECIAL SUB-DIVISION, KUNIGAL.

Notification dated 22nd September 1954.

Under Sections 25 and 26 of the Mysore Irrigation Act, 1932, as amended by Act of 1952, it is hereby notified for the information of the ryots concerned that the undermentioned Works proposed to be taken up for execution at the estimated cost against it. Any person interested may prefer his objections and suggestions, if any, within 30 days from the date of this Notification before the undermentioned (only on working days) at the office of the Assistant Engineer Special Sub-Division, Kunigal.